

IN THE UNITED STATES

PATENT AND TRADEMARK OFFICE

APPLICANT(S)

Henry Esmond Butterworth, et al.

PATENT No.:

6,941,420

ISSUE DATE:

September 6, 2005

o. ancate

SERIAL No.:

10/080,488

SEP 2.1 2006

FILING DATE:

February 22, 2002

of Correction

TITLE:

LOG-STRUCTURE ARRAY

ATTY. DKT. No.:

GB90129

CERTIFICATE OF MAILING

I hereby certify that this correspondence is being deposited with the United States Postal Service as first class mail in an envelope addressed to: Commissioner For Patents, P.O. Box 1450, Alexandria, VA 22313-1450, on the date shown below:

Dated:

9/14/06

By: />= _ // _ _ // _ _ // _ _ // _ _ // _ _ // _ _ // _ _ // _ _ // _ _ // _ _ // _ _ // _ _ // _ _ // _

BRIAN C. KUNZLER, Reg. No.:38,527

COMMISSIONER FOR PATENTS P.O. BOX 1450 ALEXANDRIA, VA 22313-1450

ATTENTION: Decision and Certificate of Correction Branch of the Patent Issue Division

REQUEST FOR CERTIFICATE OF CORRECTION

SIR:

The following errors, as more fully described below, appear in this patent.

The Applicant submits that no fee is due for correction of the errors made by the Patent and Trademark Office; OR,

The errors occurred in good faith. Correction thereof does not involve such changes in the patent as would constitute new matter or would require re-examination. A Certificate of Correction is requested. Enclosed herewith is payment in the amount of \$100.00 to cover the fee for this Certificate of Correction.

Attached hereto are duplicate Forms PTO-1050, with at least one copy that is suitable for printing.

Applicant kindly requests the following changes:

Column 9

Line 10,"The LISA controller" should read -- the LSA controller --

Please send the Certificate to:

BRIAN C. KUNZLER 8 EAST BROADWAY, SUITE 600 SALT LAKE CITY, UTAH 84111

Respectfully submitted, Brian C. Kunzler

Dated: 9/14/06

BRIAN C. KUNZLER, Reg. No.:38,527

8 East Broadway, Suite 600 Salt Lake City, Utah 84111

Telephone: (801) 994-4646

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

	No, of add'l copies @50¢ per page
ING ADDRESS OF SENDER: PATENT NO	
	•
Column 9 Line 10, "The LISA controller" should r	eadthe LSA controller
It is certified that error appears in the above-ide Patent is hereby corrected as shown below:	ntified patent and that said Letters
INVENTOR(S) : Henry Esmond Butterworth, et al.	
DATED : September 6, 2005	
PATENT NO. : 6,941,420	